


Palisa.de – Floor plan

Top floor



Information for exhibitors: Steel girders cause unequal ceiling heights at certain points. Please coordinate the positioning of booths with our technical manager.